

NAVAL FACILITIES ENGINEERING SERVICE CENTER Port Hueneme, California 93043-4370

TECHNICAL REPORT TR-2093-ENV

PERFORMANCE EVALUATION OF A
PILOT-SCALE PERMEABLE REACTIVE BARRIER
AT FORMER NAVAL AIR STATION MOFFETT FIELD,
MOUNTAIN VIEW, CALIFORNIA
(APPENDICES - VOLUME II)

by Charles Reeter, NFESC Arun Gavaskar, Battelle Bruce Sass, Battelle Neeraj Gupta, Battelle James Hicks, Battelle Sam Yoon, Battelle Tad Fox, Battelle Joel Sminchak, Battelle

August 1998

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-018

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)

2. REPORT DATE
June 1999

3. REPORT TYPE AND DATES COVERED Final: April 1996 - November 1998

4. TITLE AND SUBTITLE

PERFORMANCE EVALUATION OF A PILOT-SCALE PERMEABLE REACTIVE BARRIER AT FORMER NAVAL AIR STATION MOFFETT FIELD, MOUNTAIN VIEW, CALIFORNIA (APPENDICES - VOLUME II)

5. FUNDING NUMBERS

Contract No. N47408-95-D-0730/DO 0014

6. AUTHOR(S)

Charles Reeter - NFESC

Arun Gavaskar, Bruce Sass, Neeraj Gupta, James Hicks, Sam Yoon, Tad Fox, and Joel Sminchak - Battelle

8. PERFORMING ORGANIZATION REPORT NUMBER

TR-2093-ENV

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESSE(S)

Naval Facilities Engineering Service Center 1100 23rd Ave

Port Hueneme, CA 93043-4370

9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESSES

Department of Defense Environmental Security Technology Certification Program (ESTCP) 1725 Jefferson Davis Highway, Suite 1100 10. SPONSORING/MONITORING AGENCY REPORT

11. SUPPLEMENTARY NOTES

Arlington, VA 22203

12a. DISTRIBUTION/AVAILABILITY STATEMENT

Approved for public release; distribution is unlimited.

12b. DISTRIBUTION CODE

13. ABSTRACT (Maximum 200 words)

A pilot scale permeable reactive barrier (PRB) or treatment wall demonstration project was initiated by the US Navy EFA West at the former Naval Air Station Moffett Field site in Mountain View, California about 3 years ago. Performance evaluations and cost-benefit analyses were performed by the US Naval Facilities Engineering Service Center (NFESC) and were sponsored by the Department of Defense (DoD) Environmental Security Technology Certification Program (ESTCP). The Moffett Field PRB uses a funnel-and-gate design, where the funnel is made of interlocking steel sheet piles and the gate consists of a reactive cell filled with zero-valent granular iron. Since its construction in April 1996, groundwater monitoring was conducted on a quarterly basis to demonstrate the effectiveness of the barrier technology in capturing and remediating groundwater that contained dissolved chlorinated hydrocarbon compounds. The primary contaminants of concern at Moffett Field in the vicinity of the PRB are trichloroethene (TCE), cis-1,2 dichloroethene (cDCE), and perchloroethene (PCE) at upgradient concentrations of about 2900 micrograms per liter (ug/L), 280 ug/L, and 26 ug/L, respectively. Quarterly monitoring events included water level measurements, field parameter testing, and groundwater sampling at about 75 monitoring points. Two tracer tests using bromide solutions and flow meter testing were also completed in April and August 1997 at the site. Iron cell coring samples were collected and analyzed in December 1997 for use as indicators of reactivity and longevity. Data from the quarterly monitoring, tracer testing, and iron cell coring have been used to determine the overall barrier performance. Since the first sampling event in June 1996, concentrations of all chlorinated compounds were either reduced to non-detect (ND) or to below the drinking water maximum contaminant levels (MCLs) within the first 2-3 feet of the permeable iron cell (gate).

The iron cell coring analyses and geochemical modeling from Moffett Field indicated that changes in the inorganic chemistry were caused by precipitation of calcite, carbonates, iron-sulfide, and hydroxide compounds. Chemical precipitates are a concern because of the potential loss of reactivity and permeability in the iron cell. In general, long-term performance and life expectancies at PRB sites are unknown. The DoD ESTCP, Environmental Protection Agency, and Department of Energy are sponsoring additional performance and longevity evaluations at multiple PRB sites across the country. This is being accomplished in partnership with the RTDF PRB Action Team in an effort to gain widespread regulatory acceptance and remedial project manager confidence in using the reactive barrier technology.

14. SUBJECT TERMS			15. NUMBER OF PAGES
	ndwater; remediation; zero-valent C; TCE; PCE; DCE; VC; pump-an	· · · · · · · · · · · · · · · · · · ·	16. PRICE CODE
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	20. LIMITATION OF ABSTRACT
Unclassified	Unclassified	Unclassified	UL

Appendix F Quality Assurance

This section contains quality assurance data used to assess the validity of the groundwater sampling analyses. Results are presented for trip blanks, equipment rinsate blanks, field duplicate measurements (sampling precision), laboratory spike recoveries, and method blanks.

Table F-1a. Results of June 1996 Sampling at Moffett Field: Trip Blanks (μ g/L)

					Sam	ple ID				
		Detection		Detection		Detection		Detection	Trip	Detection
Compound	TB-101	Limit	TB-102	Limit	TB-104	Limit	TB-105	Limit	Blank	Limit
1,1-DCA	U	0.5	U	0.5	U	0.5	υ	0.5	U	0.5
1,2-DCA	U	0.5	U	0.5	υ	0.5	U	0.5	U	0.5
1,1-DCE	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
cis-1,2-DCE	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
trans-1,2-DCE	υ	0.5	U	0.5	υ	0.5	υ	0.5	υ	0.5
PCE	U	0.5	U	0.5	Ų	0.5	U	0.5	U	0.5
TCE	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Methylene Chloride	U	0.5	U	0.5	U	0.5	0.7	0.5	U	0.5
Vinyl Chloride	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Carbon Tetrachloride	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Chloroform	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
CFC-113	U	2	U	2	U	2	U	2	U	2

U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-1b. Results of June 1996 Sampling at Moffett Field: Equipment Rinsate Blanks (μ g/L)

		Sample ID										
Compound	WW-101 ^(a)	Detection Limit	WW-102 (b)	Detection Limit								
1,1-DCE	Ü	2	6.8	2								
cis-1,2-DCE	U	2	19	2								
PCE	U	2	5.6	2								
TCE	U	2	240	2								
Chloroform	61	2	U	2								

- U: The compound was analyzed but not detected at or above the specified reporting limit.
- (a) Equipment Rinsate after WW-3.
- (b) Equipment Rinsate after WIC-1.

Table F-1c. Results of June 1996 Field Precision ($\mu g/L$)

		WW-2				WW-11		-
Compound	WW-2 ^(a)	WW-2-99 ^(b)	Mean	RPD	WW-11 ^(a)	WW-11-99 ^(b)	Mean	RPD
1,1-DCA	29	18	23.5	47%	U	21	NA	NA
1,2-DCA	υ	U	NA	NA	υ	υ	NA	NA
1,1-DCE	36	26	31	32%	υ	27	NA	NA
cis-1,2-DCE	220	170	195	26%	8.2	100	54.1	170%
trans-1,2-DCE	υ	υ	NA	NA	U	U	NA	NA
PCE	12	13	12.5	8%	ט	13	NA	NA
TCE	850	850	850	0%	35	330	182.5	162%
Methylene Chloride	υ	U	NA	NA	U	U	NA	NA
Vinyl Chloride	U	υ	NA	NA	U	υ	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	υ	NA	NA
Chloroform	U	υ	NA	NA	U	υ	NA	NA
1,1,1-TCA	5.9	3.9	4.9	41%	U	3	NA	NA
CFC-113 ^(d)	1.4	3.9	2.65	94%	1.7	1.4	1.55	19%
HCFC-123 ^(d)	1.4	3.9	2.65	94%	2.0	1.4	1.7	35%
		WW-12				W9-35		
Compound	WW-12 ^(a)	WW-12-99 ^(b)	Mean	RPD	W9-35-PER ^(a)	WW-99-5 ^(c)	Mean	RPD
1,1-DCA	15	14	14.5	7%	27	31	29	14%
1,2-DCA	U	U	NA	NA	U	U	NA	NA
1,1-DCE	υ	U	NA	NA	103	133	118	26%
cis-1,2-DCE	39	36	37.5	8%	380	280	330	30%
trans-1,2-DCE	U	υ	NA	NA	U	U	NA	NA
PCE	υ	U	NA	NA	180	250	215	33%
TCE	3.4	υ	NA	NA	5,160	5,960	5,560	14%
Methylene Chloride	U	U	NA	NA	U	U	NA	NA
Vinyl Chloride	U	U	NA	NA	U	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	U	U	NA	NA
1,1,1-TCA	U	U	NA	NA	3.9	9.7	6.8	85%
CFC-113 ^(d)	υ	U	NA	NA	5.6	8.6	7.1	42%
HCFC-123 ^(d)								

RPD is defined as [|primary-duplicate|/ ½(primary+duplicate)] x 100.

⁽a) Primary sample collected using a peristaltic pump.

⁽b) Duplicate sample collected in a bailer.

⁽c) Duplicate sample collected using a dedicated in-hole pump.

⁽d) Tentatively identified compound.

NA: Not available.

U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-1d. June 1996 Lab Recovery

		WIC-1			WW-4C	
	MS	MSD		MS	MSD	
Compound	(μg/L)	(μg/L)	RPD	(μg/L)	(μg/L)	RPD
DBFM	113	103	9%	109	92	17%
1,2-DCA	98	95	3%	118	99	18%
Tol-d8	89	88	1%	93	94	1%
4-BFB	86	85	1%	98	95	3%
		WW-7D			WW-8B	
	MS	MSD		MS	MSD	
Compound	(μg/L)	(μg/L)	RPD	(μg/L)	(μg/L)	RPD
DBFM	97	91	6%	94	92	2%
1,2-DCA	87	75	15%	92	90	2%
Tol-d8	85	84	1%	104	105	1%
4-BFB	80	75	6%	94	91	3%
		WW-12			WW-13B	
	MS	MSD		MS	MSD	
Compound	(μg/L)	(μg/L)	RPD	(μg/L)	(μg/L)	RPD
DBFM	96	99	3%	65	65	0%
1,2-DCA	86	84	2%	98	100	2%
Tol-d8	89	90	1%	98	99	1%
4-BFB	81	81	0%	92	96	4%
		WW-16D				
:	MS	MSD		1		
Compound	(μg/L)	(μg/L)	RPD			
DBFM	96	91	5%			
1,2-DCA	97	100	3%			
Tol-d8	94	93	1%			
4-BFB	95	89	7%			

RPD is defined as [|MS-MSD|/ ½(MS+MSD)] x 100. QC limits for RPD are ± 25% and recoveries are within limits.

DBFM: Dibromofluoromethane.

1,2-DCA: 1,2-DCA-d4. Tol-d8: Toluene-d8.

4-BFB: 4-Bromofluorobenzene.

F-1e. June 1996 Method Blanks

	Method	Blanks Detection
	_	Limit
Compound	Result	(μg/L)
Benzene	U	2
Bromobenzene	U	2
Bromodichloromethane	U	2
Bromoform	U	2
Bromomethane	U	2
n-Butylbenzene	U	2
sec-Butylbenzene	U	2
tert-Butylbenzene	U	2
Carbon Tetrachloride	Ω	2
Chlorobenzene	U	2
Chloroethane	C	2
Chloroform	U	2
Chloromethane	U	2
2-Chlorotoluene	U	2
4-Chlorotoluene	U	2
Dibromochloromethane	U	2
1,2-Dibromo-3-chloropropane	U	2
1,2-Dibromoethane	U	2
Dibromomethane	Ü	2
1,2-Dichlorobenzene	U	2
1,3-Dichlorobenzene	U	2
1,4-Dichlorobenzene	U	2
Dichlorodifluoromethane	Ü	2
1,1-Dichloroethane	U	2
1,2-Dichloroethane	U	2
1,1-Dichloroethene	U	2
cis-1,2-Dichloroethene	U	2
trans-1,2-Dichloroethene	υ	2
1,2-Dichloropropane	U	2
1,3-Dichloropropane	U	2
2,2-Dichloropropane	U	2
1,1-Dichloropropene	U	2
Ethylbenzene	U	2
Hexachlorobutadiene		2
	U	2
Isopropylbenzene	U	2
p-Isopropylbenzene	U	2
Methylene Chloride	U	
Naphthalene	U	2
n-Propylbenzene	U	2
Styrene	U	2
1,1,1,2-Tetrachloroethane	U	2
1,1,2,2-Tetrachloroethane	υ	2
Tetrachloroethene	U	2
Toluene	U	2
1,2,3-Trichlorobenzene	U	2
1,2,4-Trichlorobenzene	U	2
1,1,1-Trichloroethane	U	2
1,1,2-Trichloroethane	U	2
Trichloroethene	U	2
Trichlorofluoromethane	U	2
1,2,3-Trichloropropane	U	2
1,2,4-Trimethylbenzene	U	2
1,3,5-Trimethylbenzene	U	2
Vinyl Chloride	U	2
Xylenes, Total	U	2
II: The compound was analyze	ad but not d	atacted at a

U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-2a. Results of September 1996 Sampling at Moffett Field: Trip Blanks ($\mu g/L$)

	SAMPLE ID									
Compound	TB-IC-1	TB-IC-2	TB-IC-3	TB-IC-4						
1,1-DCA	Ü	U	U	U						
1,2-DCA	U	U	U	U						
1,1-DCE	U	U	U	U						
cis-1,2-DCE	U	U	U	U						
PCE	U	U	U	U						
TCE	U	U	U	U						
1,1,1-Trichloroethane	U	U	U	U						
Methylene Chloride	U	U	U	U						
Vinyl Chloride	U	U	U	U						
Carbon Tetrachloride	U	U	U	U						
Chloroform	U	U	U	U						
HCFC-123	U	U	U	U						
CFC-113	U	U	U	U						
Benzene	U	U	U	U						
Toluene	U	U	U	U						
Ethylbenzene	U	U	U	U						
Xylene (Total)	U	υ	U	U						

U: The compound was analyzed but not detected at or above the reporting limit.

Table F-2b. Results of September 1996 Sampling at Moffett Field: Equipment Rinsate Blanks ($\mu g/L$)

						SAMI	PLE ID				·	
		Detection		Detection								
COMPOUND	WW-101 ^(a)	Limit	WW-102 ^(b)	Limit	WW-103 ^(c)	Limit	WW-104 ^(d)	Limit	WW-105 ^(e)	Limit	WW-106 th	Limit
1,1-DCA	U	2	U	2	U	2	U	2	U	2	U	2
1,2-DCA	U	0.5	U	0.5								
1,1-DCE	U	2	U	2	U	2	U	2	U	2	U	2
cis-1,2-DCE	U	2	2	2	U	2	U	2	U	2	U	2
PCE	U	2	2	2	U	2	U	2	U	2	U	2
TCE	1 J	2	74 E	2	U	2	U	2	U	2	U	2
1,1,1-Trichloroethane	U	2	U	2	U	2	U	2	U	2	U	2
Methylene Chloride	U	2	U	2	U	2	U	2	U	2	U	2
Vinyl Chloride	C	0.5	υ	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Carbon Tetrachloride	U	0.5	υ	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Chloroform	1 J	2	U	2	U	2	U	2	U	2	U	2
CFC-113	U	2	U	2	U	2	U	2	υ	2	U	2
Benzene	U	0.5	U	0.5								
Toluene	U	2	U	2	U	2	U	2	U	2	U	2
Ethylbenzene	U	2	U	2	U	2	U	2	U	2	J	2
Xylene (Total)	U	2	U	2	U	2	U	2	U	2	U	2

- (a) Equipment Blank after WW-18C.
- (b) Equipment Blank after WW-7D.
- (c) Equipment Blank after WW-5.
- (d) Equipment Blank after WW-3.
- (e) Equipment Blank after WW-8D.
- (f) Equipment Blank after WW-17D.
- U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-2c. Results of September 1996 Field Precision (mg/L)

		WI	C-1			ww	/-7D	
Compound	Primary	Duplicate	Mean	RPD	Primary	Duplicate	Mean	RPD
1,1-DCA	26	26	26	0%	25	26	25.5	4%
1,2-DCA	U	U	NA	NA	U	U	NA	NA
1,1-DCE	45	41	43	9%	31	35	33	12%
cis-1,2-DCE	260	240	250	8%	220 E	220 E	220	0%
PCE	15 J	17	16	13%	14	15	14.5	0%
TCE	1,400 E	1,100 E	1,250	24%	1,100 E	860 E	1,250	24%
1,1,1-Trichloroethane	U	U	NA	NA	81	8 J	8	0%
Methylene Chloride	U	7 J	NA	NA	U	8 J	NA	NA
Vinyl Chloride	U	U	NA	NA	U	υ	NA	NA
Carbon Tetrachloride	U	υ	NA	NA	U	υ	NA	NA
Chloroform	U	υ	NA	NA	U	υ	NA	NA
HCFC-123	26 N, J	NA	NA	NA	NA	NA	NA	NA
CFC-113	40	39	39.5	3%	30	29	29.5	3%
Benzene	U	3	NA	NA	υ	2 J	NA	NA
Toluene	U	U	NA	NA	U	υ	NA	NA
Ethylbenzene	U	U	NA	NA	U	U	NA	NA
Xylene (Total)	U	7 J	NA	NA	U	U	NA	NA
			'-9 ℃			WW	/-8C	
Compound	Primary	Duplicate	Mean	RPD	Primary	Duplicate	Mean	RPD
1,1-DCA	8	7	7.5	13%	27	23	25	16%
1,2-DCA	U	υ	NA	NA	U	υ	NA	NA
1,1-DCE	U	υ	NA	NA	υ	U	NA	NA
cis-1,2-DCE	U	U	NA	NA	80 E	63 E	71.5	24%
PCE	U	U	NA	NA	υ	U	NA	NA
TCE	1 J	U	NA	NA	υ	U	NA	NA
1,1,1-Trichloroethane	U	U	NA	NA	U	U	NA	NA
Methylene Chloride	υ	υ	NA	NA	U	U	NA NA	NA
Vinyl Chloride	0.4 J	U	NA	NA	υ	2	NA	NA
Carbon Tetrachloride	Ų	υ	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	U	U	NA	NA
HCFC-123	24 N, J	NA NA	NA	NA	2 N, J	NA	NA	NA
CFC-113	U	U	NA	NA	U	υ	NA	NA
Benzene	υ	U	NA	NA	U	υ	NA	NA
Toluene	U	U	NA	NA	U	υ	NA	NA NA
Ethylbenzene	U	U	NA	NA	U	U	NA	NA
Xylene (Total)	U	U WW	NA 7.12	NA	υ	U	NA 13D	NA
Compound	Primary	Duplicate	Mean	RPD	Primary	WW Duplicate	-13D Mean	RPD
1,1-DCA	24	22	23	9%	1 J	1 J	1	0%
1,2-DCA	U	U	NA NA	NA NA	U	U	NA.	NA
1,1-DCE	2	2	2	0%	2	2	2	0%
cis-1,2-DCE	87 E	85 E	71.5	24%	10	9	9.5	11%
PCF	U	U	NA NA	NA NA	U	Ü	NA	NA NA
TCE	Ü	υ	NA NA	NA NA	6	6	6	0%
1,1,1-Trichloroethane	Ü	Ŭ	NA	NA NA	U	Ü	NA	NA
Methylene Chloride	U	Ü	NA	NA NA	Ü	Ü	NA	NA NA
Vinyl Chloride	2	2	2	0%	0.4 J	0.4 J	0.4	0%
Carbon Tetrachloride	U	U	NA	NA	U	U	NA NA	NA.
Chloroform	Ü	U	NA NA	NA NA	Ü	Ü	NA NA	NA NA
HCFC-123	54 N, J	ŇA	NA	NA NA	5 N, J	NA NA	NA NA	NA NA
CFC-113	U	υ	NA NA	NA NA	U	U	NA NA	NA NA
Benzene	0.3 J	Ü	NA NA	NA NA	0.4 J	0.4 J	0.4	0%
Toluene	U	Ü	NA.	NA NA	U	U	NA	NA
Ethylbenzene	Ü	Ü	NA.	NA NA	Ü	υ	NA NA	NA
Xylene (Total)	Ü	Ü	NA.	NA NA	U	Ü	NA NA	NA NA
RPD is defined as [prir					<u> </u>			,,

NA: Not available. Calculation could not be performed due to insufficient data.

E: The amount reported exceeded the linear range of instrument calibration.

J: The compound was detected at an amount below the specified reporting limit. Consequently, the amount should be considered an estimated value.

U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-3a. Results of January 1997 Sampling at Moffett Field: Trip Blanks ($\mu g/L$)

		Sample ID										
		Detection										
Compound	TB-101	Limit	TB-102	Limit	TB-103	Limit	TB-104	Limit	TB-105	Limit	TB-106	Limit
1,1-DCA	U	2	U	2	U	2	U	2	U	2	U	2
1,2-DCA	U	0.5	U	0.5	٥	0.5	U	0.5	U	0.5	U	0.5
1,1-DCE	U	2	U	2	J	2	U	2	U	2	U	2
cis-1,2-DCE	U	2	U	2	U	2	U	2	٥	2	U	2
trans-1,2-DCE	U	2	U	2	U	2	U	2	٦	2	U	2
PCE	U	2	U	2	U	2	U	2	U	2	U	2
TCE	U	2	U	2	U	2	U	2	U	2	U	2
Methylene Chloride	U	2	Ų	2	U	2	U	2	U	2	U	2
Vinyl Chloride	U	0.5										
Carbon Tetrachloride	U	0.5										
Chloroform	U	2	U	2	U	2	U	2	υ	2	U	2
CFC-113	U	2	U	2	U	2	U	2	U	2	U	2

U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-3b. Results of January 1997 Sampling at Moffett Field: Equipment Rinsate Blanks ($\mu g/L$)

			Sample ID		· · · · · · · · · · · · · · · · · · ·					
		Detection	<u>.</u>	Detection		Detection		Detection		Detection
Compound	WW-101 ^(a)	Limit	WW-102 (b)	Limit	WW-103 ^(c)	Limit	WW-104 ^(d)	Limit	WW-105 (e)	Limit
1,1-DCA	U	2	U	2	U	2	U	2	U	2
1,2-DCA	U	0.5	כ	0.5	U	0.5	υ	0.5	J	0.5
1,1-DCE	U	2	C	2	J	2	ט	2	U	2
cis-1,2-DCE	3	2	U	2	U	2	U	2	U	2
trans-1,2-DCE	υ	2	U	2	U	2	υ	2	U	2
PCE	υ	2	U	2	U	2	U	2	U	2
TCE	9	2	U	2	U	2	υ	2	U	2
Methylene Chloride	U	2	U	2	U	2	U	2	U	2
Vinyl Chloride	U	0.5	υ	0.5	U	0.5	U	0.5	U	0.5
Carbon Tetrachloride	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Chloroform	5	2	3	2	U	2	24	2	U	2
CFC-113	U	2	U	2	U	2	U	2	U	2

- (a) Equipment Blank after WW-18C.
- (b) Equipment Blank after WW-7D.
- (c) Equipment Blank after WW-5.
- (d) Equipment Blank after WW-3.
- (e) Equipment Blank after WW-8D.
- U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-3c. Results of January 1997 Field Precision (μ g/L)

		WIC	-3			WW-	15	
Compound	WIC-3	WW-99-1	Mean	RPD	WW-15	WW-99-2	Mean	RPD
1,1-DCA	U	U	NA	NA	2	2	2	0%
1,2-DCA	U	U	NA	NA	υ	U	NA	NA
1,1-DCE	U	U	NA	NA	U	U	NA	NA
cis-1,2-DCE	220	240	230	9%	1 J	1 J	1	0%
trans-1,2-DCE	U	U	NA	NA	U	Ü	NA	NA
PCE	U	U	NA	NA	U	U	NA	NA
TCE	1900	2200	2050	15%	3	3	3	0%
Methylene Chloride	U	U	NA	NA	U	U	NA	NA
Vinyl Chloride	υ	U	NA	NA	U	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	U	U	NA	NA
CFC-113	U	U	NA	NA	U	U	NA	NA
		WIC	-8			WW-1	0D	
Compound	WIC-8	WW-99-3	Mean	RPD	WW-10D	WW-99-4	Mean	RPD
1,1-DCA	U	U	NA	NA	U	U	NA	NA
1,2-DCA	U	U	NA	NA	U	U	NA	NA
1,1-DCE	U	U	NA	NA	υ	U	NA	NA
cis-1,2-DCE	220	220	220	0%	U	U	NA	NA
trans-1,2-DCE	U	U	NA	NA	U	U	NA	NA
PCE	U	U	NA	NA	U	U	NA	NA
TCE	1200	1100	1150	9%	4	4	4	0%
Methylene Chloride	U	U	NA	NA	U	U	NA	NA
Vinyl Chloride	J	U	NA	NA	U	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	U	U	NA	NA
CFC-113	U	U	NA	NA	U	U	NA	NA
		WW-	7B		,	WW-1	.3D	
Compound	WW-7B	WW-99-5	Mean	RPD	WW-13D	WW-99-6	Mean	RPD
1,1-DCA	U	U	NA	NA	6	6	6	0%
1,2-DCA	U	U	NA	NA	U	U	NA	NA
1,1-DCE	U	U	NA	NA	U	U	NA	NA
cis-1,2-DCE	230	250	240	8%	2	2	2	0%
trans-1,2-DCE	U	U	NA	NA	U	U	NA	NA
PCE	U	U	NA	NA	U	U	NA	NA
TCE	1000	1100	1050	10%	U	U	NA	NA
Methylene Chloride	U	U	NA	NA	U	U	NA	NA
Vinyl Chloride	U	U	NA	NA	U	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	U	U	NA	NA
CFC-113	U	U	NA	NA	U	U	NA	NA
RPD is defined as [lprir	none dunli	ootal/1//pri	manı dı	nlianta\1 v	100			

RPD is defined as [|primary-duplicate|/ ½(primary+duplicate)] x 100.

NA: Not available. Calculation could not be performed due to insufficient data.

J: The compound was detected at an amount below the specified reporting limit.

U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-4a. Results of April 1997 Sampling at Moffett Field: Trip Blanks (μg/L)

			***				Sam	ple ID	.,					
		Detection												
Compound	TB-101	Limit	TB-102	Limit	TB-103	Limit	TB-104	Limit	TB-105	Limit	TB-106	Limit	TB-107	Limit
1,1-DCA	U	0.5												
1,2-DCA	U	0.5	C	0.5	υ	0.5	U	0.5	U	0.5	J	0.5	U	0.5
1,1-DCE	U	0.5	U	0.5	U	0.5	U	0.5	Ü	0.5	υ	0.5	U	0.5
cis-1,2-DCE	U	0.5	U	0.5	J	0.5	J	0.5	U	0.5	ح	0.5	ט	0.5
trans-1,2-DCE	U	0.5	J	0.5	U	0.5								
PCE	U	0.5	C	0.5	J	0.5	U	0.5	J	0.5	د	0.5	כ	0.5
TCE	U	0.5	U	0.5	U	0.5	υ	0.5	U	0.5	٥	0.5	٦	0.5
Methylene Chloride	U	4	U	4	4B	4	4B	4	U	4	U	4	J	4
Vinyl Chloride	U	1	U	1	U	1	U	1	υ	1	U	1	J	1
Carbon Tetrachloride	U	0.5												
Chloroform	U	0.5	U	0.5	U	0.5	U	0.5	٥	0.5	U	0.5	υ	0.5
CFC-113	U	0.5												

U: The compound was analyzed but not detected at or above the specified reporting limit.

B: The compound was detected in the associated method blank.

Table F-4b. Results of April 1997 Sampling at Moffett Field: Equipment Rinsate Blanks (μ g/L)

					ole ID			
		Detection		Detection		Detection		Detection
Compound	WW-101 ^(a)	Limit	WW-102 (b)	Limit	WW-103 ^(c)	Limit	WW-104 (d)	Limit
1,1-DCA	U	0.5	U	2	U	1	U	0.5
1,2-DCA	U	0.5	U	2	٥	1	U	0.5
1,1-DCE	U	0.5	υ	2	C	1	U	0.5
cis-1,2-DCE	U	0.5	υ	2	0.8J	1	4B	4
trans-1,2-DCE	U	0.5	υ	2	כ	1	0.3J	0.5
PCE	U	0.5	υ	2	0.9J	1	U	0.5
TCE	ב	0.5	U	2	41	1	C	0.5
Methylene Chloride	υ	4	25B	20	J	8	U	0.5
Vinyl Chloride	U	1	د	0.8	ر	0.32	NA	NA
Carbon Tetrachloride	υ	0.5	U	2	U	1	2	0.5
Chloroform	2	0.5	2J	2	2	1	IJ	0.5
CFC-113	υ	0.5	U	2	U	1	U	1
		Detection		Detection		Detection		Detection
Compound	WW-105 (e)	Limit	WW-106 ^(f)	Limit	WW-107 ^(g)	Limit	WW-108 ^(h)	Limit
1,1-DCA	C	0.5	U	0.5	U	0.5	U	0.5
1,2-DCA	υ	0.5	υ	0.5	U	0.5	U	0.5
1,1-DCE	υ	0.5	U	0.5	υ	0.5	U	0.5
cis-1,2-DCE	υ	0.5	υ	0.5	U	0.5	Ü	0.5
trans-1,2-DCE	U	0.5	د	0.5	U	0.5	Ü	0.5
PCE	J	0.5	U	0.5	U	0.5	0.6	0.5
TCE	J	0.5	U	0.5	3	0.5	10	0.5
Methylene Chloride	U	4	J	4	U	4	υ	4
Vinyl Chloride	U	1	J	1	U	1	U	1
Carbon Tetrachloride	ט	0.5	Ú	0.5	U	0.5	U	0.5
Chloroform	1	0.5	2	0.5	0.8	0.5	2	0.5
CFC-113	U	0.5	U	0.5	U	0.5	0.6	0.5

- (a) Equipment Blank after WW-5.
- (b) Equipment Blank after WW-18C.
- (c) Equipment Blank after WW-2.
- (d) Equipment Blank after WW-17C.
- (e) Equipment Blank after WW-1C.
- (f) Equipment Blank after WW-8C.
- (g) Equipment Blank after WW-13D.
- (h) Equipment Blank after WIC-8.

NA: Not available.

- B: The compound was detected in the associated method blank.
- J: The compound was detected at an amount below the specified reporting limit.
- U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-4c. Results of April 1997 Field Precision (μ g/L)

		WW-	9C			ww	-2	
Compound	WW-9C	WW-99-1	Mean	RPD	WW-2	WW-99-2	Mean	RPD
1,1-DCA	8	8	8	0%	25	U	NA	NA
1,2-DCA	U	J	NA	NA	35	U	NA	NA
1,1-DCE	U	U	NA	NA	٦	33 J	NA	NA
cis-1,2-DCE	U	0.6	NA	NA	U	270	NA	NA
trans-1,2-DCE	U	C	NA	NA	υ	U	NA	NA
PCE	0.6	U	NA	NA	270	υ	NA	NA
TCE	U	Ų	ÑĀ	NA	220 в	2,000	1,110	160%
Methylene Chloride	U	U	NA	NA	15 J	460 в	237.5	187%
Vinyl Chloride	U	U	NA	NA	U	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	1,900	U	NA	NA
Chloroform	U	U	NA	NA	24 J	U	NA	NA
CFC-113	U	U	NA	NA	U	υ	NA	NA
		WW-1	8D			WW-	12	
Compound	WW-18D	WW-99-3	Mean	RPD	WW-12	WW-99-4	Mean	RPD
1,1-DCA	1	8	4.5	156%	15	14	14.5	7%
1,2-DCA	U	Ü	NA	NA	2 J	U	NA	NA
1,1-DCE	U	U	NA	NA	U	U	NA	NA
cis-1,2-DCE	U	0.9	NA	NA	U	90	NA	NA
trans-1,2-DCE	U	U	NA	NA	U	U	NA	NA
PCE	4	U	NA	NA	97	U	NA	NA
TCE	Ü	Ü	NA	NA	υ.	6	NA	NA
Methylene Chloride	U	U	NA	NA	U	u	NA	NA
Vinyl Chloride	U	U	NA	NA NA	U	U	NA	NA
Carbon Tetrachloride	3	U	NA NA	NA NA	6	U	NA NA	NA NA
Chloroform	U	U	NA.	NA.	Ű	U	NA NA	NA NA
CFC-113	U	U	NA	NA NA	U	U	NA NA	NA NA
		ww-		, .	l – j	WW-1		
Compound								
n Commonnu	I WW-11)	WW.99.5	Mean	RPD	WW-13D	WW-99-6	Mean	RPD
	WW-1D	WW-99-5	Mean 6	RPD	WW-13D	WW-99-6	Mean 6.5	RPD 15%
1,1-DCA	6	6	6	0%	6	7	6.5	15%
1,1-DCA 1,2-DCA	6 U	6 υ	6 NA	0% NA	6 U	7 U	6.5 NA	15% NA
1,1-DCA 1,2-DCA 1,1-DCE	6 U	6 5 5	6 NA NA	0% NA NA	6 U	7 U U	6.5 NA NA	15% NA NA
1,1-DCA 1,2-DCA 1,1-DCE <i>cis</i> -1,2-DCE	6 U U	6 U U 3	6 NA NA NA	0% NA NA NA	6 0 0	7 U U	6.5 NA NA NA	15% NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE	6 U U U	6 U 3 U	6 NA NA NA	0% NA NA NA	6 U U U	7 U U 1	6.5 NA NA NA	15% NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE	6 U U U U 3	6 U 3 U	6 NA NA NA NA	0% NA NA NA NA	6 U U U U	7 U U 1 U	6.5 NA NA NA NA	15% NA NA NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE	6 U U U 3	6 0 3 0 0	6 NA NA NA NA NA	0% NA NA NA NA NA	6 U U U U 1	7 U 1 U U 0.4 J	6.5 NA NA NA NA NA	15% NA NA NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride	6 U U U U 3 3	6 0 3 0 0	6 NA NA NA NA NA NA	0% NA NA NA NA NA NA	6 U U U U 1 U	7 U U 1 U U 0.4 J	6.5 NA NA NA NA NA NA	15% NA NA NA NA NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride	6 U U U 3 U	6 U 3 U U	6 NA NA NA NA NA NA NA	0% NA NA NA NA NA NA NA	6 U U U 1 U	7 U 1 U U 0.4 J U	6.5 NA NA NA NA NA NA NA	15% NA NA NA NA NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride	3 0 0 0 0 0 0	6 U 3 U U U	6 NA NA NA NA NA NA NA	0% NA	6 U U U 1 U U U 0.4 J	7 U 1 U U 0.4 J U	6.5 NA NA NA NA NA NA NA	15% NA NA NA NA NA NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform	3 0 0 0 0 0 0	6 U 3 U U U U	6 NA NA NA NA NA NA NA NA	0% NA	6 U U U 1 U U U U	7 U U 1 U U 0.4 J U U	6.5 NA NA NA NA NA NA NA NA	15% NA NA NA NA NA NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride	3 0 0 0 0 0 0	6 0 3 0 0 0 0 0	6 NA NA NA NA NA NA NA NA	0% NA	6 U U U 1 U U U 0.4 J	7 U 1 U U 0.4 J U	6.5 NA NA NA NA NA NA NA	15% NA NA NA NA NA NA NA NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113	3 0 0 0 0 0 0 0 0 0 0 0 0	6 U 3 U U U U U WIC	6 NA NA NA NA NA NA NA NA NA NA	0% NA	6 U U U 1 U U U 0.4 J U	7 U U 1 U U 0.4 J U U U	6.5 NA NA NA NA NA NA NA NA NA	15% NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound	6 U U U 3 U U U U U	6 U U 3 U U U U U U WIC WW-99-7	6 NA NA NA NA NA NA NA NA NA NA NA	0% NA	6 U U U 1 U U U 0.4 J U	7 U U U U U U U U U U U U U U U U U U U	6.5 NA	15% NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA	6 U U U 3 U U U U U U WIC-8	6 U U 3 U U U U U WIC WW-99-7 23 J	6 NA	0% NA	6 U U U 1 U U 0.4 J U U B: The cor the ass	7 U U U U U U U U U U U U U U U U U U U	6.5 NA	15% NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA	6 U U U 3 3 U U U U U WIC-8 19 J 21 J	6 U U 3 U U U U U WIC WW-99-7 23 J	6 NA	0% NA	6 U U U 1 U U 0.4 J U U B: The cor the ass J: The cor	7 UUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUU	6.5 NA	15% NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE	6 U U U 3 3 U U U U WIC-8 19 J 21 J U	6 U U U U U U U WIC WW-99-7 23 J U 23 J	6 NA	0% NA	6 U U U 1 U U 0.4 J U U B: The cor the ass J: The cor an amo	7 U U U U U U U U U U U U U U U U U U U	6.5 NA	15% NA
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE	6 U U U 3 3 U U U U U V V V V V V V V V V	6 U U 3 U U U U WIC WW-99-7 23 J U 23 J 220	6 NA	0% NA	6 U U U 1 U U 0.4 J U U B: The cor the ass J: The cor an amor	7 U U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE	6 U U U 3 U U U U U U U U WIC-8 19 J 21 J U U U U	6 U U U U U U U U WIC WW-99-7 23 J U 23 J 220 U	6 NA	0% NA	B: The corting the ass J: The corting the	7 U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE	6 U U U U 3 U U U U U U WIC-8 19 J 21 J U U 200	6 U U U U U U U U U U U U U U U U U U U	6 NA NA NA NA NA NA NA NA NA NA NA NA NA	0% NA	B: The corting the ass J: The corting the	7 U U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE	6 U U U U U U U U U U U U U U U U U U U	6 U U U U U U U U WIC WW-99-7 23 J U 23 J 220 U 13 J 1,300	6 NA NA NA NA NA NA NA NA NA NA NA NA NA	0% NA	B: The corting the ass J: The corting the	7 U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride	6 U U U U U U U U U U U U U U U U U U U	6 U U U U U U U U U U U U U	6 NA NA NA NA NA NA NA NA NA NA NA NA NA	0% NA	B: The corting the ass J: The corting the	7 U U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride	6 U U U U U U U U U U U U U U U U U U U	6 U U U U U U U U WIC WW-99-7 23 J U 23 J 220 U 13 J 1,300	6 NA NA NA NA NA NA NA NA NA NA NA NA NA	0% NA	B: The corting the ass J: The corting the	7 U U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Vinyl Chloride Carbon Tetrachloride	6 U U U U U U U U U U U U U U U U U U U	6 U U U U U U U U U U U U U	6 NA NA NA NA NA NA NA NA NA NA NA NA NA	0% NA	B: The corting the ass J: The corting the	7 U U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Vinyl Chloride Chloroform	6 U U U U U U U U U U U U U U U U U U U	6 U U U U U U U U U U U U U U U U U U U	6 NA NA NA NA NA NA NA NA NA NA NA NA NA	0% NA	B: The corting the ass J: The corting the	7 U U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N
1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Carbon Tetrachloride Chloroform CFC-113 Compound 1,1-DCA 1,2-DCA 1,1-DCE cis-1,2-DCE trans-1,2-DCE PCE TCE Methylene Chloride Vinyl Chloride Vinyl Chloride Carbon Tetrachloride Vinyl Chloride Carbon Tetrachloride	6 U U U U U U U U U U U U U U U U U U U	6 U U U U U U U U U U WIC WW-99-7 23 J U 23 J 220 U 13 J 1,300 U U	6 NA NA NA NA NA NA NA NA NA NA NA NA NA	0% NA	B: The corting the ass J: The corting the	7 U U U 1 U U 0.4 J U U U U U U U U U U U U U U U U U U U	6.5 NA	NA N

RPD is defined as [|primary-duplicate|/ ½(primary+duplicate)] x 100.

NA: Not available. Calculation could not be performed due to insufficient data.

Table F-5a. Results of October 1997 Sampling at Moffett Field: Trip Blanks ($\mu g/L$)

				······································	Sam	ple ID				
		Detection		Detection		Detection		Detection	Trip	Detection
Compound	TB-101	Limit	TB-102	Limit	TB-104	Limit	TB-105	Limit	Blank	Limit
1,1-DCA	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
1,2-DCA	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
1,1-DCE	U	0.5	U	0.5	J	0.5	٥	0.5	U	0.5
cis-1,2-DCE	U	0.5	U	0.5	U	0.5	٦	0.5	U	0.5
trans-1,2-DCE	U	0.5	U	0.5	Ü	0.5	J	0.5	U	0.5
PCE	U	0.5	U	0.5	U	0.5	٦	0.5	U	0.5
TCE	U	0.5	U	0.5	U	0.5	٦	0.5	U	0.5
Methylene Chloride	U	0.5	U	0.5	U	0.5	0.7	0.5	U	0.5
Vinyl Chloride	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Carbon Tetrachloride	U	0.5	U	0.5	υ	0.5	٥	0.5	U	0.5
Chloroform	U	0.5	U	0.5	U	0.5	ح	0.5	U	0.5
CFC-113	U	2	U	2	U	2	U	2	U	2

U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-5b. Results of October 1997 Sampling at Moffett Field: Equipment Rinsate Blanks (μ g/L)

					Sampl	e ID				
Compound	WW-101 ^(a)	Detection Limit	WW-102 ^(b)	Detection Limit	WW-103 ^(c)	Detection Limit	WW-104 (d)	Detection Limit	WW-105 ^(e)	Detection Limit
1,1-DCA	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
1,2-DCA	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
1,1-DCE	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
cis-1,2-DCE	0.5	0.5	U	0.5	U	0.5	U	0.5	U	0.5
trans-1,2-DCE	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
PCE	U	0.5	0.9	0.5	U	0.5	U	0.5	U	0.5
TCE	11	0.5	16	0.5	U	0.5	U	0.5	U	0.5
Methylene Chloride	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Vinyl Chloride	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Carbon Tetrachloride	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
Chloroform	U	0.5	U	0.5	U	0.5	U	0.5	U	0.5
CFC-113	U	2	υ	2	U	2	U	2	U	2

- (a) Equipment Rinsate after WW-16A.
- (b) Equipment Rinsate after WIC-10.
- (c) Equipment Rinsate after WW-18C.
- (d) Equipment Rinsate after WW-13D.
- (e) Equipment Rinsate after WW-8D.
- U: The compound was analyzed but not detected at or above the specified reporting limit.

Table F-5c. Results of October 1997 Sampling Field Precision (μg/L)

		WW-1	0C			WW-1	3C	
Compound	WW-10C	WW-99-1	Mean	RPD	WW-13C	WW-99-2	Mean	RPD
1,1-DCA	0.7	0.8	0.75	13%	6	U	NA	NA
1,2-DCA	U	U	NA	NA	3	U	NA	NA
1,1-DCE	υ	υ	NA	NA	٦	U	NA	NA
cis-1,2-DCE	1	2	1.5	67%	1	2	1.5	67%
trans-1,2-DCE	ט	U	NA	NA	U	U	NA	NA
PCE	U	U	NA	NA	J	U	NA	NA
TCE	10	10	10	0%	J	U	NA	NA
Methylene Chloride	U	U	NA	NA	U	U	NA	NA
Vinyl Chloride	٦	U	NA	NA	J	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	U	U	NA	NA
CFC-113	U	U	NA	NA	U	U	NA	NA
		WW-	14			WW	-5	
Compound	WW-14	WW-99-3	Mean	RPD	WW-5	WW-99-5	Mean	RPD
1,1-DCA	1	1	1	0%	2	2	2	0%
1,2-DCA	U	J	NA	NA	U	U	NA	NA
1,1-DCE	U	U	NA	NA	U	U	NA	NA
cis-1,2-DCE	0.6	0.8	0.7	29%	U	U	NA	NA
trans-1,2-DCE	U	U	NA	NA	U	U	NA	NA
PCE	U	U	NA	NA	Ü	Ü	NA	NA
TCE	٥	U	NA	NA	U	U	NA	NA
Methylene Chloride	U	U	NA	NA	U	U	NA	NA
Vinyl Chloride	U	U	NA	NA	U	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	Ü	U	NA	NA
CFC-113	U	U	NA	NA	υ	U	NA	NA
		WW-	8D			WIC	-8	
Compound	WW-8D	WW-99-6	Mean	RPD	WIC-8	WW-99-7	Mean	RPD
1,1-DCA	16	16	16	0%	23	19	21	19%
1,2-DCA	U	U	NA	NA	U	U	NA	NA
1,1-DCE	U	υ	NA	NA	35	29	32	19%
cis-1,2-DCE	58	44	51	28%	170 D	290 D	230	52%
trans-1,2-DCE	U	C	NA	NA	3	1	2	100%
PCE	U	U	NA	NA	17	15	16	13%
TCE	0.8	0.7	0.75	13%	1,300 D	1,400 D	1,350	8%
Methylene Chloride	U	U	NA	NA	U	U	NA	NA
Vinyl Chloride	1	1	1	0%	U	U	NA	NA
Carbon Tetrachloride	U	U	NA	NA	U	U	NA	NA
Chloroform	U	U	NA	NA	U	U	NA	NA
CFC-113	U	U	NA	NA	14	U	NA	NA
RPD is defined as floring				alianta\l	. 100			

RPD is defined as [|primary-duplicate|/ ½(primary+duplicate)] x 100.

NA: Not available. Calculation could not be performed due to insufficient data.

U: The compound was analyzed but not detected at or above the specified reporting limit.

D: The compound was detected in an analysis performed at a secondary dilution.

Table F-5d. October 1997 Lab Precision

		WW-3			WW-1D	
	MS	MSD		MS	MSD	
Compound	(μg/L)	(μg/L)	% RPD	(μg/L)	$(\mu g/L)$	% RPD
Target Chlorinated Solven	ts					
PCE	9.350	8.303	12%	10.296	10.481	2%
TCE	10.932	12.062	10%	10.003	10.403	4%
cis-1,2-DCE	77.434	116.930	41%*	10.200	10.053	1%
Vinyl Chloride	8.509	9.478	11%	8.875	9.664	9%
Other Chlorinated Solvent	S					
1,1-DCA	20.712	31.901	43%*	12.916	12.781	1%
1,2-DCA	8.451	10.007	17%	8.776	8.926	2%
1,2-Dichlorobenzene	9.526	9.614	1%	9.604	9.656	1%
1,3-Dichlorobenzene	9.938	10.237	3%	10.512	10.428	1%
1,4-Dichlorobenzene	9.934	9.804	1%	9.968	10.164	2%
1,1-DCE	10.558	10.697	1%	10.161	10.380	2%
trans-1,2-DCE	8.845	11.378	25%	9.909	9.972	1%
1,2-Dichloropropane	9.139	10.003	9%	8.802	9.118	4%
cis-1,3-Dichloropropene	8.800	8.292	6%	8.833	8.905	1%
trans-1,3-Dichloropropene	8.618	8.226	5%	8.769	8.725	1%
1,1,2,2-Tetrachloroethane	8.983	9.430	5%	8.849	9.071	2%
1,1,1-Trichloroethane	9.142	12.017	27%*	11.094	11.193	1%
1,1,2-Trichloroethane	8.336	11.165	29%*	7.877	7.844	0%
Carbon Tetrachloride	9.100	8.993	1%	11.582	12.373	7%
Chlorobenzene	9.237	10.591	14%	10.783	10.692	1%
Chloromethane	7.719	9.783	24%	7.334	7.796	6%
Chloroethane	8.930	12.367	32%*	9.876	10.508	6%
Chloroform	9.092	13.392	38%*	10.355	9.916	4%
Methylene Chloride	8.916	12.330	32%*	9.211	9.066	2%
Bromodichloromethane	8.836	10.933	21%	9.616	9.914	3%
Dibromochloromethane	8.646	10.077	15%	9.872	9.774	1%
Trichlorofluoromethane	7.419	5.983	21%	8.828	9.957	12%
Other Organic Analytes						
Acetone	11.528	21.669	61%*	4.152	4.702	12%
Bromomethane	6.882	10.094	38%*	7.990	8.309	4%
Benzene	9.174	10.176	10%	9.572	9.768	2%
Bromoform	8.944	10.026	11%	9.617	9.408	2%
2-Butanone	9.196			5.237	5.340	2%
Carbon Disulfide	9.841			9.916		2%
Ethylbenzene	9.400			11.224		0%
2-Hexanone	11.924			6.311	6.599	4%
4-Methyl-2-pentanone	11.797		49%*	5.682	6.554	14%
Styrene	9.147			9.552	10.596	10%
Toluene	8.933		11%	9.350	9.602	3%
Vinyl Acetate	5.026			3.261	3.018	8%
<i>m,p</i> -Xylene	18.870			22.517	22.171	2%
o-Xylene	9.233			11.204	11.072	1%
Xylenes	28.390	30.764	8%	34.940	34.444	1%

RPD is defined as [|MS-MSD|/½(MS+MSD)] x 100.

* Values outside of QC limits (± 25%).

Table F-5e. October 1997 MS and MSD Recovery Rate (%)

			W	W-3				···	wv	V-1D		
		Spike			MS	MSD		Spike			MS	MSD
	Unspiked	Level	MS	MSD	Recovery	Recovery	Unspiked	Level	MS	MSD	Recovery	Recovery
Compound	(μg/L)	$(\mu g/L)$	(μg/L)	(μg/L)	(%)	(%)	(μg/L)	$(\mu g/L)$	(μg/L)	(μg/L)	(%)	(%)
Target Chlorinated Solven	ts				•							
PCE	0.00	10.00	9.35	8.30	94%	83%	0.00	10.00	10.30	10.48	103%	105%
TCE	1.60	10.00	10.93	12.06	93%	105%	0.00	10.00	10.00	10.40	100%	104%
cis-1,2-DCE	62.52	10.00	77.43	116.93	149%*	544%*	0.00	10.00	10.20	10.05	102%	101%
Vinyl Chloride	0.00	10.00	8.51	9.48	85%	95%	0.00	10.00	8.88	9.66	89%	97%
Other Chlorinated Solvent	s											
1,1-DCA	11.93	10.00	20.71	31.90	88%	200%*	3.17	10.00	12.92	12.78	97%	96%
1,2-DCA	0.00	10.00	8.45	10.01	85%	100%	0.00	10.00	8.78	8.93	88%	89%
1,2-Dichlorobenzene	0.00	10.00	9.53	9.61	95%	96%	0.00	10.00	9.60	9.66	96%	97%
1,3-Dichlorobenzene	0.00	10.00	9.94	10.24	99%	102%	0.00	10.00	10.51	10.43	105%	104%
1,4-Dichlorobenzene	0.00	10.00	9.93	9.80	99%	98%	0.00	10.00	9.97	10.16	100%	102%
1,1-DCE	2.22	10.00	10.56	10.70	83%	85%	0.00	10.00	10.16	10.38	102%	104%
trans-1,2-DCE	0.00	10.00	8.85	11.38	88%	114%	0.00	10.00	9.91	9.97	99%	100%
1,2-Dichloropropane	0.00	10.00	9.14	10.00	91%	100%	0.00	10.00	8.80	9.12	88%	91%
cis-1,3-Dichloropropene	0.00	10.60	8.80	8.29	83%	78%	0.00	10.60	8.83	8.91	83%	84%
trans-1,3-Dichloropropene	0.00	9.40	8.62	8.23	92%	88%	0.00	9.40	8.77	8.73	93%	93%
1,1,2,2-Tetrachloroethane	0.00	10.00	8.98	9.43	90%	94%	0.00	10.00	8.85	9.07	88%	91%
1,1,1-Trichloroethane	0.00	10.00	9.14	12.02	91%	120%	0.00	10.00	11.09	11.19	111%	112%
1,1,2-Trichloroethane	0.00	10.00	8.34	11.17	83%	112%	0.00	10.00	7.88	7.84	79%	78%
Carbon Tetrachloride	0.00	10.00	9.10	8.99	91%	90%	0.00	10.00	11.58	12.37	116%	124%
Chlorobenzene	0.00	10.00	9.24	10.59	92%	106%	0.00	10.00	10.78	10.69	108%	107%
Chloromethane	0.00	10.00	7.72	9.78	77%	98%	0.00	10.00	7.33	7.80	73%*	78%
Chloroethane	0.52	10.00	8.93	12.37	84%	119%	0.00	10.00	9.88	10.51	99%	105%
Chloroform	0.00	10.00	9.09	13.39	91%	134%*	0.00	10.00	10.36	9.92	104%	99%
Methylene Chloride	0.00	10.00	8.92	12.33	89%	123%	0.00	10.00	9.21	9.07	92%	91%
Bromodichloromethane	0.00	10.00	8.84	10.93	88%	109%	0.00	10.00	9.62	9.91	96%	99%
Dibromochloromethane	0.00	10.00	8.65	10.08	86%	101%	0.00	10.00	9.87	9.77	99%	98%
Trichlorofluoromethane	0.00	10.00	7.42	5.98	74%*	60%*	0.00	10.00	8.83	9.96	88%	100%
Other Organic Analytes												
Acetone	0.00	10.00	11.53	21.67	115%	217%*	0.00	10.00	4.15	4.70	42%*	47%*
Bromomethane	0.00	10.00	6.88	10.09	69%	101%	0.00	10.00	7.99	8.31	80%	83%

Table F-5e. October 1997 MS and MSD Recovery Rate (%) (Continued)

			W	W-3					wv	V-1D		
		Spike			MS	MSD		Spike			MS	MSD
	Unspiked	Level	MS	MSD	Recovery	Recovery	Unspiked	Level	MS	MSD	Recovery	Recovery
Compound	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(%)	(%)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(%)	(%)
Benzene	0.00	10.00	9.17	10.18	92%	102%	0.00	10.00	9.57	9.77	96%	98%
Bromoform	0.00	10.00	8.94	10.03	89%	100%	0.00	10.00	9.62	9.41	96%	94%
2-Butanone	0.00	10.00	9.20	7.26	92%	73%*	0.00	10.00	5.24	5.34	52%*	53%*
Carbon Disulfide	0.00	10.00	9.84	7.55	98%	75%	0.00	10.00	9.92	9.73	99%	97%
Ethylbenzene	0.00	10.00	9.40	10.21	94%	102%	0.00	10.00	11.22	11.22	112%	112%
2-Hexanone	0.00	10.00	11.92	7.77	119%	78%	0.00	10.00	6.31	6.60	63%*	66%*
4-Methyl-2-pentanone	0.00	10.00	11.80	7.14	118%	71%*	0.00	10.00	5.68	6.55	57%*	66%*
Styrene	0.00	10.00	9.15	7.04	91%	70%*	0.00	10.00	9.55	10.60	96%	106%
Toluene	0.00	10.00	8.93	10.01	89%	100%	0.00	10.00	9.35	9.60	94%	96%
Vinyl Acetate	0.00	10.00	5.03	0.94	50%	9%*	0.00	10.00	3.26	3.02	33%*	30%*
<i>m,p</i> -Xylene	0.00	20.00	18.87	19.27	94%	96%	0.00	20.00	22.52	22.17	113%	111%
o-Xylene	0.00	10.00	9.23	10.45	92%	105%	0.00	10.00	11.20	11.07	112%	111%
Xylene	0.00	30.00	28.39	30.76	95%	103%	0.00	30.00	34.94	34.44	116%	115%

a. Recovery (%) is defined as [|MS(D) Level–Unspiked Sample|/Spike Concentration] x 100.

* Values outside of QC limits (75 - 125 %).

Table F-5f. October 1997 Method Blanks (%)

	Method	Blanks
		Detection
		Limit
Compound	Result	(μg/L)
Target Chlorinated Solven	ts	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
PCE	U	0.5
TCE	Ü	0.5
cis-1,2-DCE	U	0.5
Vinyl Chloride	U	0.5
Other Chlorinated Solvents		0.0
1,1-DCA	U	0.5
1,2-DCA	U	0.5
1,2-Dichlorobenzene	U	0.5
1,3-Dichlorobenzene	U	0.5
1,4-Dichlorobenzene	U	0.5
1,1-DCE	U	0.5
trans-1,2-DCE	U	0.5
1,1,2,2-Tetrachloroethane	U	0.5
1,1,1-Trichloroethane	U	0.5
1,1,2-Trichloroethane	υ	0.5
Bromoform	U	0.5
Carbon Tetrachloride	U	0.5
Chloroethane	U	0.5
Chloroform	U	0.5
Methylene Chloride	U	0.5
Bromodichloromethane	Ü	0.5
Dibromochloromethane	U	0.5
Trichlorotrifluoromethane	υ	2
Trichlorofluoromethane	U	0.5
Other Organic Analytes		
Acetone	U	2
Benzene	U	0.5
Bromomethane	U	0.5
2-Butanone	U	2
Carbon Disulfide	U	2
Chloromethane	υ	0.5
Chlorobenzene	υ	0.5
1,2-Dichloropropane	υ	0.5
cis-1,3-Dichloropropene	U	0.5
trans-1,3-Dichloropropene	U	0.5
Ethylbenzene	U	0.5
2-Hexanone	υ	2
4-Methyl-2-pentanone	U	2
Styrene	U	0.5
Toluene	υ	0.5
Vinyl Acetate	υ	2
Xylene	υ	0.5
U: The analyte was not deter	-4	مطاف مدده

U: The analyte was not detected at or above the reporting limit.

Appendix G Cost Issues

This section contains supplementary cost data used to project the cost of a full-scale permeable reactive barrier at Moffett Field. In this scenario, the full-scale permeable barrier would be constructed in two sections: the Site 9 wall would be 600 ft in length and the northern wall would be 1,100 ft in length.

Table G-1 lists cost elements used in the calculation according to EPA Work Breakdown Structure (WBS) number. Individual cost items were developed by NFESC based on preliminary projections prepared by site representatives (Tetra Tech).

Table G-2 contains present value cost comparison data for a full-scale permeable reactive barrier and pump-and-treat system at Moffett Field. A real rate of return of 8% was assumed in the calculation.

Table G-3 contains actual value cost comparison data for a full-scale permeable reactive barrier and pump-and-treat system at Moffett Field.

Figures G-1 through G-4 are sand channel maps for four discrete depths in the A aquifer.

Table G-1. Projected Cost of A Full-Scale Barrier at Moffett Field

WBS#	Cost Elements	Unit	Quantity	Unit Cost	Total Cost
	Capital Cost				
	Total Capital Cost			1	\$4,992,363
	Site Preparation	-			\$115,258
	Procurement/equipment/material/subs	ea	1	\$7,893	\$7,893
	Line locator/utility survey	ea	1	\$17,984	\$17,984
	Traffic control plan	ea	1	\$2,100	\$2,100
	Construction scheduling	ea	1	\$2,100	\$2,100
	Coord./mutual understanding meeting	ea	1	\$1,080	\$1,080
-	Preconstruction meeting	ea	1	\$1,080	\$1,080
33.01.04.01	Office trailer	month	3	\$440	\$1,320
33.01.04.10	Toilets	month	5	\$57	\$287
33.01.04.11	Barricades	ft	9,216	\$8	\$77,414
33.01.05	Construct temporary utilities				\$2,000
	Power connection	ea	1	\$1,000	\$1,000
	Telephone connection	ea	1	\$1,000	\$1,000
	Treatability Tests, Site Characterization, and Design				\$292,820
	Site characterization	lsum	1	\$100,000	\$100,000
	Bench-scale tests	lsum	1	\$75,000	\$75,000
	Concrete characterization	ea	12	\$1,000	\$12,000
	Asphalt test	ea	6	\$705 \$265	\$4,230 \$1,590
	Welding	ea Imm	1	\$100,000	\$1,390
33.02.91 33.03	Engineering design and modeling Construction	lsum	1	\$100,000	\$3,740,825
	Construction equipment mobilization	ea	1	\$39,693	\$39,693
	Trench Installation	- Ca	1	\$557,812	\$37,073
33.03.03.70	a. Trench excavation	yd ³	19,667	\$6	\$118,000
	b. Borrow, filter media, hauled	yd³	13,111	\$25	\$322,009
			† 	\$3	
	c. Backfilling	yd ³	19,667		\$67,063
	d. Grading	yd ²	756	\$1	\$567
	e. Compaction	yd ³	19,667	\$3 6125	\$49,363
22.06.00	f. Monitoring station Gates Installation	ea	6	\$135 \$1,847,910	\$810
33.06.90	a. Iron filing material, including freight	ton	2,518	\$1,047,910	\$881,300
	b. Iron freight	ton	2,518	\$330 \$75	\$188,850
	c. Iron prep and placement	ft ²	3,540		
	d. Iron/slurry transition	ea	3,340		\$720,000
33.03.90	Receiving and Handling Iron	ton	2,518		\$22,360
33.03.90	Funnel walls installation	ton	2,510	\$1,237,584	
33.06.03	Slurry Walls	ft ²	81,420		\$895,620
33.06.05	Sheet Piling	ft ²	16,284	\$21	\$341,964
33.21.04	Demobilization of Construction Equipment and Facilities		10,204	\$57,826	Ψ,5-1,704
	Demobilization of Construction Equipment	ea	1		\$39,693
	Surface restoration total	yd ²	756		1
33.05.04.90 33.06	Monitoring Wells Installation	ea	23		
33.18	On-Site Spoils Disposal (Other than commercial)		-	\$2,000	\$16,370
	Load/haul soils to on-site soil pile	yd ³	3,918	\$3	
	Pumping water into holding tank	day	18		\$6,498
33.19	Off-Site Spoils Disposal (Commercial)	 ,	 	T	\$387,989
33.19.02	Transportation to disposal facility				\$66,581
1	Load/haul/unload removed asphalt	yd ³	6,534	\$10	1
-	Landfilling fees for removed asphalt	yd ³	6,534	t	
33.20	Site Demobilization and Post-Construction Reports	- ''	1 3,334	 	\$122,053
	Site cleanup	hr	320	\$19	
33.21.01	Removal of Temporary Facilities	- 111	1 320	\$81,021	1

Table G-1. Projected Cost of A Full-Scale Barrier at Moffett Field (Continued)

WBS#	Cost Elements	Unit	Quantity	Unit Cost	Total Cost
33.19.02.01	Load/haul/unload removed asphalt	yd ³	6,534	\$10	\$66,581
	Landfilling fees for removed asphalt	yd ³	6,534	\$39	\$254,826
33.20	Site Demobilization and Post-Construction Reports				\$122,053
	Site cleanup	hr	320	\$19	\$6,032
33.21.01	Removal of Temporary Facilities			\$81,021	44,002
33.21.01.01	Office trailer	ca	3	\$440	\$1,320
	Toilets	ea	5	\$57	\$287
	Barricades	1f	9,216	\$8	\$77,414
	Removal of temporary utilities - Power connection	ea	1	\$1,000	\$1,000
	Removal of temporary utilities - Telephone connection	ea	1	\$1,000	\$1,000
33.21	Post Construction Submittals			\$35,000	\$1,000
33.21.06	Final QA/QC report	lsum	1	\$15,000	\$15,000
	Construction document report	lsum	1	\$10,000	\$10,000
	As-built drawings	lsum	1	\$10,000	\$10,000
33.99	Distributive Costs (Overheads Support)		1	420,000	\$271,047
33.99.01	Supervision/management	lsum	1	\$180,430	\$180,430
33.99.08	Temporary construction facilities	lsum	1	\$4,333	\$4,333
33.99.13	Vehicles for personnel	lsum	1	\$19,600	\$19,600
33.99.15	Health and safety	lsum	1	\$5,000	\$5,000
33.99.19	Home office costs	lsum	1	\$61,684	\$61,684
	Total estimated capital costs				\$4,992,363
			<u>. </u>		
	Operating and Maintenance Costs				
1	Operating Cost Incurred Every Year				\$72,278
33	Operating Cost Incurred Every Year Maintenance Cost Incurred in Each of Years 10, 20, and 30.				\$72,278 \$267,538
33	Operating Cost Incurred Every Year Maintenance Cost Incurred in Each of Years 10, 20, and 30				\$72,278 \$267,538
33.02	Maintenance Cost Incurred in Each of Years 10, 20, and 30				\$267,538
		lsum	1	\$15,000	\$267,538 \$44,936
33.02	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling		1 26	\$15,000 \$536	\$267,538 \$44,936 \$15,000
33.02 33.02.07	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis	lsum sample			\$267,538 \$44,936
33.02 33.02.07 33.02.09	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis	sample	26	\$536	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000
33.02 33.02.07 33.02.09 33.02.91	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials	sample lsum	26 1	\$536 \$1,000	\$267,538 \$44,936 \$15,000 \$13,936
33.02 33.02.07 33.02.09 33.02.91 33.02.92	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report	sample lsum	26 1	\$536 \$1,000	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years)	sample lsum lsum	26 1 1	\$536 \$1,000 \$15,000	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs	sample lsum lsum	26 1 1	\$536 \$1,000 \$15,000	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year)	sample lsum lsum	26 1 1	\$536 \$1,000 \$15,000	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management	lsum lsum ea	26 1 1	\$536 \$1,000 \$15,000 \$267,538	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager	sample lsum lsum ea	26 1 1 1	\$536 \$1,000 \$15,000 \$267,538	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator	sample lsum lsum ea hr hr	26 1 1 1 1 80 80	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator c. Project Superintendent	sample lsum lsum ea hr hr	26 1 1 1 1 80 80	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29 \$38	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320 \$4,560
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator c. Project Superintendent d. Health & Safety Officer	sample lsum lsum ea hr hr hr	26 1 1 1 1 80 80 120 40	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29 \$38 \$29	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320 \$4,560 \$1,160
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99 33.99.01.00	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator c. Project Superintendent d. Health & Safety Officer e. Quality control superintendent	sample lsum lsum ea hr hr hr	26 1 1 1 1 80 80 120 40	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29 \$38 \$29	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320 \$4,560 \$1,160
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99 33.99.01.00	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator c. Project Superintendent d. Health & Safety Officer e. Quality control superintendent Vehicles for personnel	sample lsum lsum ea hr hr hr	26 1 1 1 80 80 120 40	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29 \$38 \$29 \$46	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320 \$4,560 \$1,160 \$3,680
33.02 33.02.07 33.02.09 33.02.91 33.06 33.06.91 33.99 33.99.01.00 33.99.13 33.99.13 33.99.15	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator c. Project Superintendent d. Health & Safety Officer e. Quality control superintendent Vehicles for personnel Pickup trucks	sample lsum lsum ea hr hr hr	26 1 1 1 80 80 120 40	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29 \$38 \$29 \$46	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320 \$4,560 \$1,160 \$3,680
33.02 33.02.07 33.02.09 33.02.91 33.06 33.06.91 33.99 33.99.01.00 33.99.13 33.99.13 33.99.15	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator c. Project Superintendent d. Health & Safety Officer e. Quality control superintendent Vehicles for personnel Pickup trucks Health and Safety	sample lsum lsum ea hr hr hr hr hr hr hr	26 1 1 1 80 80 120 40 80	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29 \$38 \$29 \$46	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320 \$4,560 \$1,160 \$3,680
33.02 33.02.07 33.02.09 33.02.91 33.02.92 33.06 33.06.91 33.99 33.99.01.00 33.99.13 33.99.13 33.99.15 33.99.15	Maintenance Cost Incurred in Each of Years 10, 20, and 30 Monitoring, Sampling, and Analysis Field sampling Laboratory chemical analysis Sampling materials Data evaluation, report Maintenance (once every ten years) Iron replacement costs Distributive Costs (every year) Supervision/Management a. Project Manager b. Field project administrator c. Project Superintendent d. Health & Safety Officer e. Quality control superintendent Vehicles for personnel Pickup trucks Health and Safety Personal protective equipment	sample lsum lsum ea hr hr hr hr hr hr hr	26 1 1 1 80 80 120 40 80	\$536 \$1,000 \$15,000 \$267,538 \$46 \$29 \$38 \$29 \$46 \$980 \$1,000	\$267,538 \$44,936 \$15,000 \$13,936 \$1,000 \$15,000 \$267,538 \$267,538 \$27,342 \$3,680 \$2,320 \$4,560 \$1,160 \$3,680

Table G-2. Present Value Comparison of Pump-and-Treat and Permeable Reactive Barrier Alternatives

1							
	Discount						
	Factor			PV(P&T) -			PV(PRB) -
Year	(8% APR)	P&T Cost	PV(P&T)	Cumulative	PRB Cost	PV(PRB)	Cumulative 042
0	1.000	\$1,412,086	\$1,412,086	\$1,412,086	\$4,910,943	\$4,910,943	\$4,910,943
1	0.926	\$694,746	\$643,283	\$2,055,369	\$72,278	\$66,924	\$4,977,867
2	0.857	\$694,746	\$595,633	\$2,651,002	\$72,278	\$61,967	\$5,039,834
3	0.794	\$694,746	\$551,512	\$3,202,514	\$72,278	\$57,377	\$5,097,210
4	0.735	\$694,746	\$510,659	\$3,713,173	\$72,278	\$53,126	\$5,150,337
5	0.681	\$694,746	\$472,832	\$4,186,005	\$72,278	\$49,191	\$5,199,528
6	0.630	\$694,746	\$437,808	\$4,623,813	\$72,278	\$45,547	\$5,245,075
7	0.583	\$694,746	\$405,378	\$5,029,191	\$72,278	\$42,174	\$5,287,249
8 ^(a)	0.540	\$694,746	\$375,350	\$5,404,540	\$72,278	\$39,050	\$5,326,299
9	0.500	\$694,746	\$347,546	\$5,752,086	\$72,278	\$36,157	\$5,362,456
10	0.463	\$694,746	\$321,802	\$6,073,888	\$339,816	\$157,401	\$5,519,856
11	0.429	\$694,746	\$297,965	\$6,371,853	\$72,278	\$30,999	\$5,550,855
12	0.397	\$694,746	\$275,893	\$6,647,746	\$72,278	\$28,703	\$5,579,558
13	0.368	\$694,746	\$255,457	\$6,903,203	\$72,278	\$26,576	\$5,606,134
14	0.340	\$694,746	\$236,534	\$7,139,737	\$72,278	\$24,608	\$5,630,742
15	0.315	\$694,746	\$219,013	\$7,358,750		\$22,785	\$5,653,527
16	0.292	\$694,746	\$202,790	\$7,561,539		\$21,097	\$5,674,624
17	0.270	\$694,746	\$187,768	\$7,749,308	\$72,278	\$19,534	\$5,694,159
18	0.250	\$694,746	\$173,860	\$7,923,167	\$72,278	\$18,087	\$5,712,246
19	0.232	\$694,746	\$160,981	\$8,084,148	\$72,278	\$16,748	\$5,728,994
20	0.215	\$694,746	\$149,057	\$8,233,205	\$339,816	\$72,907	\$5,801,901
21	0.199	\$694,746	\$138,015	\$8,371,220	\$72,278	\$14,358	\$5,816,259
22	0.184	\$694,746	\$127,792	\$8,499,012	\$72,278	\$13,295	\$5,829,554
23	0.170	\$694,746	\$118,326	\$8,617,338	\$72,278	\$12,310	\$5,841,864
24	0.158	\$694,746	\$109,561	\$8,726,899	\$72,278	\$11,398	\$5,853,262
25	0.146		\$101,445	\$8,828,344		\$10,554	\$5,863,816
26	0.135	\$694,746	\$93,931	\$8,922,275		\$9,772	\$5,873,588
27	0.125	\$694,746	\$86,973	\$9,009,248		\$9,048	\$5,882,636
28	0.116	\$694,746	\$80,531	\$9,089,779		\$8,378	\$5,891,015
29	0.107	\$694,746	\$74,565	\$9,164,344		\$7,757	\$5,898,772
30	0.099	\$694,746	\$69,042	\$9,233,386		\$33,770	\$5,932,542
31	0.092	\$694,746	\$63,928	\$9,297,314		\$6,651	\$5,939,193
32	0.085		\$59,192	\$9,356,506		\$6,158	\$5,945,351
33	0.079	f	\$54,808	\$9,411,314		\$5,702	\$5,951,053
34	0.073		\$50,748	\$9,462,062	1	\$5,280	\$5,956,332
35	0.068		\$46,989	\$9,509,051		\$4,888	\$5,961,221
36	0.063		\$43,508	\$9,552,559		\$4,526	\$5,965,747
37	0.058	•	\$40,285	\$9,592,844		\$4,191	\$5,969,938
38	0.054		\$37,301	\$9,630,145		\$3,881	\$5,973,819
39	0.050		\$34,538	\$9,664,684		\$3,593	\$5,977,412
40	0.046		\$31,980	\$9,696,663		\$15,642	\$5,993,054
41	0.043		\$29,611	\$9,726,274		\$3,081	\$5,996,135
42	0.039		\$27,418	\$9,753,692		\$2,852	\$5,998,987
43	0.037	t .	\$25,387	\$9,779,078		\$2,641	\$6,001,628
44	0.034		\$23,506		1	\$2,445	\$6,004,074
45	0.031		\$21,765		1	\$2,264	\$6,006,338
46	0.029		\$20,153				\$6,008,435
47	0.027	i i	\$18,660				\$6,010,376
48	0.025	\$694,746	\$17,278	\$9,880,440			\$6,012,173
49	0.023	\$694,746	\$15,998	\$9,896,438		\$1,664	\$6,013,838
50	0.021	\$694,746	\$14,813	\$9,911,251	\$339,816	\$7,245	\$6,021,083

(a) At year 8, the estimated costs for the P&T and PRB alternatives are approximately equivalent.

Table G-3. Actual Value Comparison of Pump-and-Treat and Permeable Reactive Barrier Alternatives

Years of	Ac	tual Cost for	Actual Cost for			
Operation		PRB	P&T			
0	\$	4,910,943	\$	1,412,086		
1	\$	4,983,221	\$	2,106,832		
2	\$	5,055,499	69	2,801,578		
3	\$	5,127,777	\$	3,496,324		
4	\$	5,200,055	\$	4,191,070		
5	\$	5,272,333	\$	4,885,816		
6 ^(a)	\$	5,344,611	\$	5,580,562		
7	\$	5,416,889	\$	6,275,308		
8	\$	5,489,167	\$	6,970,054		
9	\$	5,561,445	\$	7,664,800		
10 ^(b)	\$	5,901,261	\$	8,359,546		
11	\$	5,973,539	\$	9,054,292		
12	\$	6,045,817	\$	9,749,038		
13	\$	6,118,095	\$	10,443,784		
14	\$	6,190,373	\$	11,138,530		
15	\$	6,262,651	\$	11,833,276		
16	\$	6,334,929	\$	12,528,022		
17	\$	6,407,207	\$	13,222,768		
18	\$	6,479,485	\$	13,917,514		
19	\$	6,551,763	\$	14,612,260		
20 ^(b)	\$	6,891,579	\$	15,307,006		
21	\$	6,963,857	\$	16,001,752		
22	\$	7,036,135	\$	16,696,498		
23	\$	7,108,413	\$	17,391,244		
24	\$	7,180,691	\$	18,085,990		
25	\$	7,252,969	\$	18,780,736		
26	\$	7,325,247	\$	19,475,482		
27	\$	7,397,525	\$	20,170,228		
28	\$	7,469,803	\$	20,864,974		
29	\$	7,542,081	\$	21,559,720		
30 ^(b)	\$	7,881,897	\$	22,254,466		

Years of	Actual Cost for		Actual Cost for			
Operation		PRB		P&T		
31	\$	7,954,175	\$	22,949,212		
32	\$	8,026,453	\$	23,643,958		
33	\$	8,098,731	\$	24,338,704		
34	\$	8,171,009	\$	25,033,450		
35	\$	8,243,287	\$	25,728,196		
36	\$	8,315,565	\$	26,422,942		
37	\$	8,387,843	\$	27,117,688		
38	\$	8,460,121	\$	27,812,434		
39	\$	8,532,399	\$	28,507,180		
40 ^(b)	\$	8,872,215	\$	29,201,926		
41	\$	8,944,493	\$	29,896,672		
42	\$	9,016,771	\$	30,591,418		
43	\$	9,089,049	\$	31,286,164		
44	\$	9,161,327	\$	31,980,910		
45	\$	9,233,605	\$	32,675,656		
46	\$	9,305,883	\$	33,370,402		
47	\$	9,378,161	\$	34,065,148		
48	\$	9,450,439	\$	34,759,894		
49	\$	9,522,717	\$	35,454,640		
50 ^(b)	\$	9,862,533	\$	36,149,386		

(a) At year 6, the estimated costs for the P&T and PRB alternatives are approximately equivalent. (b) Barrier maintenance cost of \$267,538 added every 10 years.




Figure G-1. Sand Channel Map (Depth 5 to 18 ft bgs) at Moffett Field (Source: NFESC, 1995)




Figure G-2. Sand Channel Map (Depth 15 to 28 ft bgs) at Moffett Field (Source: NFESC, 1995)




Figure G-3. Sand Channel Map (Depth 29 to 41 ft bgs) at Moffett Field (Source: NFESC, 1995)




Figure G-4. Sand Channel Map (Depth 38 to 51 ft bgs) at Moffett Field (Source: NFESC, 1995)